

TALARIA FORK (TL4000)



Item	Parte Ref. No.	Descripción	Unit	Precio (CLP)
1	40480-56005-000	Fr. Fork Assy. (TALARIA)	Set	\$ 1.043.000
2	40490-56005-000	Fr. Fork L. Legs (TALARIA)	Pcs	\$ 683.000
3		Fr. Fork R. Legs (TALARIA)	Pcs	\$ -
4	40481-56005-000	Lower Crown/Steer Assy.	Pcs	\$ 127.000
5	40496-56005-000	Upper Crown	Pcs	\$ 55.500
6	40486-56005-000	Fr. Wheel Axle (TALARIA)	Set	\$ 50.000
7	40487-56005-000	Set Bolt (TALARIA)	Pcs	\$ 6.000
8	40499-56005-000	Fr. fork fender(TALARIA)	Set	\$ 31.500
9	40485-56005-000	Steering Buffer Rubber	Pcs	\$ 16.500
10	40492-56005-000	Oil Seal	Pcs	\$ 72.000